PHOENIX


Features and Benefits

- Magnetic technology offers robust performance.
- 100% Non-contacting design (no bearings or bushings) provides an extremely long life and is tolerant to harsh environments.
- Simple two piece design (magnet rotor + encoder) for easy alignment and installation.
- Two channel incremental quadrature output.
- Mounting holes for a 2-bolt pattern 1.00" BHC x 0.120" O.D.
- Target magnet for standard shaft sizes from 2 mm to 3/8 Inch. Custom bore sizes available.
- Optional universal target magnet hub to accomodate both metric (2, 3, 4, 5 & 6mm) and inch (1/8, 3/16 & 1/4 In.) shaft diameters.
- Options for 32 2500 pulse per channel per revolution.
- Customizable lead wires, cables, and/or connectors.


Application Example



Kit - Encoder with Target Magnet Shown with shaft pass through hole and single ended wiring Wire color order varies with part configuration



Electrical Circuit



Phoenix America, LLC 4717 Clubview Drive Fort Wayne, IN 46804 T: Within USA: 1 888 801 1422 Outside USA: +1 260 432 9664 www.phoenixamerica.com sales@phoenixamerica.com © Copywrite PAL 2023, PDS DK 05/23

Page 1

Absolute Maximum Ratings

Table 2.1


Characteristic	Symbol	Rating	Units
Forward Supply Voltage	V _{cc}	12	V
Reverse Supply Voltage	V _{RCC}	-0.3	V
Storage Temperature	Τ _s	150	°C
ESD (HMB, 100pF/1.5Kohm)		2	kV
Operating Temperature		-40 to 125	°C

Electrical Specifications - (Vcc = 5V, Ambient Temperature = 23 °C)

Table 2.2

Characteristic	Symbol	Min.	Тур.	Max.	Unit
Supply Voltage	V _{cc}	3.3	5	6	V
Supply Current	I _{cc}	-	14	20	mA
Duty Cycle	-	40	50	60	%
Phase	-	70	90	110	°e
Output Frequency	f _{out}	-	-	42	kHz


Output Waveforms



Phoenix America, LLC 4717 Clubview Drive Fort Wayne, IN 46804 T: Within USA: 1 888 801 1422 Outside USA: +1 260 432 9664 www.phoenixamerica.com sales@phoenixamerica.com © Copywrite PAL 2023, PDS DK 05/23




Encoder Physical Outline



Encoder Mounting Guidelines

Concentricity of the encoder housing to the target magnet is critical for optimal encoder performance. Considering the following during the design phase will ensure concentricity and ease of assembly.

- Tight molding tolerances allow for the outside diameter of the encoder to be used to locate the encoder housing concentric to the motor shaft and target magnet. A machined pocket on the motor endbell works well for alignment. Recommended pocket is 0.015" to 0.020" deep and 1.215" in diameter.
- Extending the shaft through the optional shaft pass through hole is an easy way to align the encoder housing to the motor shaft and target magnet. Simply position the encoder so that the shaft is centered concentrically in the shaft pass through hole.
- If previous two methods of alignment are not used it is recommended that the encoder be fastened to the motor using #5-40 or M3 mounting screws. The slightly larger diameter of the #5-40 and M3 screws will compensate for some of the tolerance allowed when using the standard recommended #4-40 or M2.5 mounting screws.



Phoenix America, LLC 4717 Clubview Drive Fort Wayne, IN 46804 T: Within USA: 1 888 801 1422 Outside USA: +1 260 432 9664 www.phoenixamerica.com sales@phoenixamerica.com © Copywrite PAL 2023, PDS DK 05/23

Page 3



Target Magnet Physical Outline - Molded (Mounting Style A)





Table 4.	1			
Bore Size (Inch)	Motor Shaft OD Size (nominal)	NEMA Guide Shaft Tolerance	Magnet Bore MIN. (Inch)	Magnet Bore MAX. (Inch)
079	2 mm (.0787")		.0777	.0807
118	3 mm (.1181")		.1171	.1201
125	1/8 in (.1250")		.1240	.1270
156	5/32 in (.1563")		.1553	.1583
157	4 mm (.1575")		.1565	.1595
188	3/16 in (.1875")		.1865	.1895
197	5 mm (.1969")	+0.0000"/-0.0005"	.1959	.1989
236	6 mm (.2364")		.2354	.2384
250	1/4 in (.2500")		.2490	.2520
276	7 mm (.2758")		.2747	.2777
313	5/16 in (.3125")		.3115	.3145
315	8 mm (.3150")		.3140	.3170
375	3/8 in (.3750")		.3740	.3770

Other bore sizes available upon request. Contact sales@phoenixamerica.com.

Target Magnet Mounting Guidelines - Molded (Mounting Style A) For Slip Fit Application

- Proper alignment of the target magnet to the encoder sensing element is critical for optimal encoder performance. Insure that the target magnet is mounted to the specified height shown in the diagram below.
- A machined step on the motor shaft provides a quick and repeatable method for positioning the target magnet. Spacers or other fixturing should be used to properly position the target magnet if no mechanical locating features are on the shaft.
- Various adhesives can be used to bond the target magnet to the motor shaft. Shaft alloys, operating environment, and shaft speed
 and acceleration should be taken into consideration when selecting an appropriate bonding agent. Loctite threadlockers and retaining
 compounds have proved effective in bonding the target magnet to the motor shaft. Loctite 263 and 2760 threadlockers and Loctite
 638 and 680 retaining compounds are good candidates. These materials have been effective in past experience; testing under actual
 operating conditions should be used to qualify any bonding material.
- For best results, the motor shaft should be clean and free of any oils, lubricants, or solvents.
- Apply adhesive around the leading edge of the shaft and inside the hole in the rotor. Use a rotating motion when assembling the target magnet to the shaft to insure good adhesive coverage.
- The use of primers and activators can be used to improve bond strength and cure rate.
- For non-critical applications or for fast bonding for evaluation, a cyanoacrylate adhesive (super glue) can be used. Loctite 401 and 410 have proven effective for quick bonding applications.






Phoenix America, LLC 4717 Clubview Drive Fort Wayne, IN 46804 T: Within USA: 1 888 801 1422 Outside USA: +1 260 432 9664 www.phoenixamerica.com sales@phoenixamerica.com © Copywrite PAL 2023, PDS DK 05/23

Subject to change without notice

Page 4

PHOENIX


Target Magnet Physical Outline - Universal Hub (Mounting Style U)



Assembly Guidelines

Step 1


Attach two of the desired hub size on each side of the magnet. Make sure the flats are in-line with each other.



Step 2 Use the insertion tool to push the target magnet assembly **straight** onto the shaft until the bottom face of the hub is resting on the 2 mm gap tool.


tip - Support the bottom of the motor with a fixture or holding clamp.





Step 4

Manually spin the shaft to verify that the shaft/magnet is not interfering with the encoder.



Encoder Cross Section - note the magnet assembly and shaft are not in contact with the encoder housing or the motor housing.

With shaft pass-Step 3a through option Place the Step 2a encoder onto the motor and Insert an additional hub secure with #4 piece as shown. This or M3 screws. is used as a space filler to match the opening in the encoder housing. Encoder Cross Section - note the top face of the filler hub should be flush with the top face of the encoder housing as shown by the

Page 5


Phoenix America, LLC 4717 Clubview Drive Fort Wayne, IN 46804 T: Within USA: 1 888 801 1422 Outside USA: +1 260 432 9664

www.phoenixamerica.com sales@phoenixamerica.com © Copywrite PAL 2023, PDS DK 05/23

arrow pointer.

PHOENIX Α Μ Е RIC

Wiring (Single ended option depicted)




- UL Style 2464, CSA
- Temperature Rating: 105°C


Tabl	e 6.	1
------	------	---

Single Ended Wiring			
	Leads	Cable	Connector Pin-Out
Ch A	Yellow	Brown	1
Ch B	Blue	Orange	2
Gnd	Black	Black	3
Vcc	Red	Red	4

Custom lengths and insulation materials available. Contact sales@phoenixamerica.com.



Part Number Description



Phoenix America, LLC 4717 Clubview Drive Fort Wayne, IN 46804

T: Within USA: 1 888 801 1422 Outside USA: +1 260 432 9664

www.phoenixamerica.com sales@phoenixamerica.com © Copywrite PAL 2023, PDS DK 05/23